

C38 Link should rotate free after full tightening of ST019 Screw. Please increase the chamfers on C38 holes in case of binding. Please do the same for both holes.

