

Next time: move rear to type 1 and bgap = 3.2 (lower value due to 100 deg bent hard springs); try more steering bumpshims; adjusting AM06 shimming; testing +/- 1mm front lower arm shim; low diff & spool; FBS in Front Rear along with baseline test raising uppper links to 3.5mm total height (adding 1.75mm); retesting chassis flex with top decks / rear C26 / AM105H; ESC software tests