

Tips - How to improve.

• Drivers feel suddenly for initial motor rotation while operating throttle.

Setting neutral / high-point \Rightarrow Turning neutral position to high side by throttle trim \Rightarrow Returning one trim position and no sound from situations for no motor rotation (Beep from motor) # Trim adjustment is minimum step.

Drivers feel sudden motor rotation on Mid-speed range while operating throttle.

Feeling small torque on Mid-speed range from putting boost or turbo \Rightarrow (1) Changing setting of power mode and adjusting putting boost or turbo or (2) Setting adjustable rate control (ARC) of throttle into plus side or minus side.

Some differences due to motor's characteristic, so please adjust while actual operation.

You can experience the more advanced system with the set of SUPER VORTEX ZERO and RX-472. http://sanwa-denshi.com/rc/car/receiver/rx-472.html