

Associated TC8 Gear Chart

Internal ratio= 1.9

Upper limit= 111

Lower limit= 99

	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86
15																				10.64	10.77	10.89
16																			9.86	9.98	10.09	10.21
17																		9.16	9.28	9.39	9.50	9.61
18																	8.55	8.66	8.76	8.87	8.97	9.08
19																8.00	8.10	8.20	8.30	8.40	8.50	8.60
20															7.51	7.60	7.70	7.79	7.89	7.98	8.08	8.17
21														7.06	7.15	7.24	7.33	7.42	7.51	7.60	7.69	7.78
22													6.65	6.74	6.82	6.91	7.00	7.08	7.17	7.25	7.34	7.43
23												6.28	6.36	6.44	6.53	6.61	6.69	6.77	6.86	6.94	7.02	7.10
24											5.94	6.02	6.10	6.18	6.25	6.33	6.41	6.49	6.57	6.65	6.73	6.81
25										5.62	5.70	5.78	5.85	5.93	6.00	6.08	6.16	6.23	6.31	6.38	6.46	6.54
26									5.33	5.41	5.48	5.55	5.63	5.70	5.77	5.85	5.92	5.99	6.07	6.14	6.21	
27								5.07	5.14	5.21	5.28	5.35	5.42	5.49	5.56	5.63	5.70	5.77	5.84	5.91		
28							4.82	4.89	4.95	5.02	5.09	5.16	5.23	5.29	5.36	5.43	5.50	5.56	5.63			
29						4.59	4.65	4.72	4.78	4.85	4.91	4.98	5.04	5.11	5.18	5.24	5.31	5.37				
30					4.37	4.43	4.50	4.56	4.62	4.69	4.75	4.81	4.88	4.94	5.00	5.07	5.13					
31				4.17	4.23	4.29	4.35	4.41	4.47	4.54	4.60	4.66	4.72	4.78	4.84	4.90						
32			3.98	4.04	4.10	4.16	4.22	4.28	4.33	4.39	4.45	4.51	4.57	4.63	4.69							
33		3.80	3.86	3.92	3.97	4.03	4.09	4.15	4.20	4.26	4.32	4.38	4.43	4.49								
34	3.63	3.69	3.74	3.80	3.86	3.91	3.97	4.02	4.08	4.14	4.19	4.25	4.30									
35	3.53	3.58	3.64	3.69	3.75	3.80	3.85	3.91	3.96	4.02	4.07	4.13										
36	3.43	3.48	3.54	3.59	3.64	3.69	3.75	3.80	3.85	3.91	3.96											
37	3.34	3.39	3.44	3.49	3.54	3.59	3.65	3.70	3.75	3.80												
38	3.25	3.30	3.35	3.40	3.45	3.50	3.55	3.60	3.65													
39	3.17	3.22	3.26	3.31	3.36	3.41	3.46	3.51														
40	3.09	3.14	3.18	3.23	3.28	3.33	3.37															
41	3.01	3.06	3.10	3.15	3.20	3.24																
42	2.94	2.99	3.03	3.08	3.12																	
43	2.87	2.92	2.96	3.00																		
44	2.81	2.85	2.89																			