

WTF3010BH9

Diff measured at 234 on Arrowmax v2 meter

Next time: move rear to type 1 and bgap = 4; 100 deg bent hard springs; 1mm under AM06; testing +/-1mm front lower arm shim; low diff & spool; FBS in Front Rear along with baseline test raising uppper links to 3.5mm total height (adding 1.75mm)