

XRAY T3'12

● ☒ - APPLIED S - SOFT M - MEDIUM H - HARD

The diagram illustrates the balance assembly with the following settings:

- Left Side:**
 - BALANCE /g: 5
 - ECCENTER /mm: STANDARD ☒ (1mm), DIFF. POSITION UP ☒ (DOWN ☐)
 - LOWER SUSP. BLOCK: SOLID ☒ (2 pcs ☐)
- Right Side:**
 - BALANCE /g: 5
 - ECCENTER /mm: STANDARD ☒ (1mm), DIFF. POSITION UP ☒ (DOWN ☐)
 - LOWER SUSP. BLOCK: SOLID ☒ (2 pcs ☐)
- Center:**
 - BALANCE /g: 0

VFR 6.0 (C) XRAY